













Zebex 3220+

[Configuration Sheet]



Barcode	Function
	Enter Configuration Mode
	Restore Default Factory Settings
	Exit Configuration Mode
	Enter Configuration Mode
	Restore USB Defaults
	Exit Configuration Mode
	Enter Configuration Mode
	International Keyboard Mode
	Add Prefix
	Add Tilde
	Validate Prefix
	Set Prefix
	Exit Configuration Mode